

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,928,348 B1
DATED : August 9, 2005
INVENTOR(S) : Lightner et al.


Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings sheet, consisting of Fig. 8, should be deleted and replaced with the drawing sheet, consisting of Fig.8, as shown on the attached page.

Signed and Sealed this

Seventh Day of March, 2006



JON W. DUDAS
Director of the United States Patent and Trademark Office

200

KNOW WHAT YOUR CAR IS THINKING.

Log Out Help

230 Jane Doe 1998 TOYOTA CAMRY

231 2001 TOYOTA COROLLA 239 Last CARreader Update: Jan 26 09:35:35 PST

232 VIN#: WPOCA2993XS651063 Emissions Vehicle Mileage: 13096 miles

[Customer Profile](#) [Vehicle Check](#) [Service](#) [Records](#)

[Back to Vehicle Check](#) [Vehicle-Related Information](#)

Inspection/Maintenance

235

Found 7 entries with information on your vehicle's performance.

Parameter	3/15/2001 17:33:05	3/15/2001 16:53:05	3/15/2001 16:29:27	3/15/2001 8:00:11	3/13/2001 12:00:14	3/11/2001 16:14:11	3/15/2001 16:00:00
	230 DTCs	none	none	P0100	none	none	none
MIL Light	off	off	on	off	off	off	off
Misfire Monitor	comp	incomp	incomp	comp	comp	comp	comp
Fuel System	comp						
Comprehensive Comp	comp	comp	comp	comp	comp	comp	comp
Catalyst	comp						
Heated Catalyst	nsup						
Evaporative System	comp						
Secondary Air System	comp						
A/C Sys Refrigerant	comp						
Oxygen Sensor	comp						
Heated Oxygen Sensor	comp						
Exhaust Gas Recirc	comp						
Status	<input type="checkbox"/>						

226 205 206 208 210 212 214 216 218

228

FIG. 8